

Modifications in SAF-HOLLAND Original parts numbers: 12.03.2010 – 30.06.2011

	Date	Part number	Note	Part number	Comment
1	30.06.2011	3155103100	no longer available		
2	30.06.2011	3155103200	no longer available		
3	30.06.2011	4029103800	no longer available		
4	30.06.2011	3155103101	no longer available		
5	30.06.2011	3155103201	no longer available		
6	30.06.2011	3155104600	replaced by	3155108600	
7	30.06.2011	3357018000	no longer available		
8	07.06.2011	4029102201	replaced by	3304004901	
9	07.06.2011	4029102200	replaced by	3304004901	
10	06.06.2011	3057396810	no longer available		
11	31.05.2011	3213000406	no longer available		
12	30.05.2011	4315004500	no longer available		
13	19.05.2011	4375100712	replaced by	4375100912	
14	17.05.2011	3268001701	no longer available		
15	17.05.2011	3434350300	replaced by	3434350302	
16	16.05.2011	3434311400	no longer available		
17	16.05.2011	3434311500	no longer available		
18	16.05.2011	3434311600	no longer available		
19	16.05.2011	3434311700	no longer available		
20	16.05.2011	3434311800	no longer available		
21	16.05.2011	3434311900	no longer available		
22	16.05.2011	3434312100	no longer available		
23	16.05.2011	3434312000	no longer available		
24	16.05.2011	3434312500	no longer available		
25	16.05.2011	3434312600	no longer available		
26	16.05.2011	3434312400	no longer available		
27	16.05.2011	3434312300	no longer available		
28	16.05.2011	4200100700	no longer available		
29	16.05.2011	3434312700	no longer available		
30	16.05.2011	3434312800	no longer available		
31	04.05.2011	3050102200	no longer available		
32	06.04.2011	4200001200	no longer available		
33	30.03.2011	1064022100	no longer available		
34	28.03.2011	3155103602	replaced by	3155108700	
35	25.03.2011	1368003600	no longer available		
36	25.03.2011	3434380100	replaced by	3434382000	
37	18.03.2011	3434333000	no longer available		
38	16.03.2011	3434385400	replaced by	3434385702	
39	16.03.2011	3434385401	replaced by	3434385702	
40	16.03.2011	3434385402	replaced by	3434385702	
41	16.03.2011	3434385403	replaced by	3434385702	
42	16.03.2011	3434385700	replaced by	3434385702	
43	16.03.2011	3434385701	replaced by	3434385702	
44	10.03.2011	3304004905	no longer available		
45	11.02.2011	663110051	no longer available		

Modifications in SAF-HOLLAND Original parts numbers: 12.03.2010 – 30.06.2011

	Date	Part number	Note	Part number	Comment
46	07.02.2011	1402002200	no longer available		
47	04.02.2011	20000170	no longer available		
48	04.02.2011	1230001000	no longer available		
49	03.02.2011	3424200500	replaced by	3424200400	
50	01.02.2011	RK-05329	no longer available		
51	26.01.2011	1064005000	no longer available		
52	26.01.2011	659002192	no longer available		
53	19.01.2011	3155102800	replaced by	3155108800	
54	19.01.2011	3155102801	replaced by	3155108800	
55	19.01.2011	3155102802	replaced by	3155108800	
56	18.01.2011	4051006000	replaced by	662102206	
57	13.01.2011	1230004800	replaced by	1230013800	
58	12.01.2011	2376007401	replaced by	2376007001	
59	12.01.2011	1304003800	no longer available		
60	12.01.2011	3434385800	replaced by	3434385403	
61	12.01.2011	2376007501	replaced by	2376007101	
62	12.01.2011	2376007601	replaced by	2376007201	
63	12.01.2011	2376007701	replaced by	2376007301	
64	11.01.2011	3424200800	replaced by	3424200500	Knorr 19,5" (3424200400= Knorr 22,5")
65	30.12.2010	4175026200	replaced by	3434350101	
66	30.12.2010	4175021100	replaced by	3434350101	
67	30.12.2010	4175014900	replaced by	3434350601	
68	30.12.2010	4175024900	replaced by	3434350203	
69	30.12.2010	4175022800	replaced by	3434350203	
70	30.12.2010	4175024000	replaced by	3434350203	
71	30.12.2010	4175026100	replaced by	3434350101	
72	30.12.2010	4175015400	replaced by	3434350101	
73	30.12.2010	4175024800	replaced by	3434350101	
74	30.12.2010	4175026000	replaced by	3434350101	
75	30.12.2010	4175024700	replaced by	3434350302	
76	30.12.2010	4175024100	replaced by	3434351600	
77	30.12.2010	4175024200	replaced by	3434351600	
78	30.12.2010	4175014100	replaced by	3434350501	
79	30.12.2010	4175013900	replaced by	3434350601	
80	30.12.2010	4175029500	replaced by	3434350601	
81	30.12.2010	4175015000	replaced by	3434350601	
82	30.12.2010	4175014000	replaced by	3434350601	
83	30.12.2010	4175029600	replaced by	3434350601	
84	30.12.2010	4175023500	replaced by	3434351500	
85	30.12.2010	4175023700	replaced by	3434351500	
86	30.12.2010	4175027900	replaced by	3434351500	
87	30.12.2010	4175023600	replaced by	3434351500	
88	30.12.2010	4175023800	replaced by	3434351500	
89	30.12.2010	4175028000	replaced by	3434351500	
90	21.12.2010	1064015100	no longer available		

Modifications in SAF-HOLLAND Original parts numbers: 12.03.2010 – 30.06.2011

	Date	Part number	Note	Part number	Comment
91	16.12.2010	2307106100	no longer available		
92	16.12.2010	2307105100	no longer available		
93	15.12.2010	3434380500	replaced by	3434382000	
94	15.12.2010	650410373	no longer available		
95	01.12.2010	2376100901	replaced by	2376101300	
96	01.12.2010	2376100900	replaced by	2376101300	
97	01.12.2010	3080005400	replaced by	3080005402	
98	01.12.2010	3080006000	replaced by	3080006001	
99	01.12.2010	3080005401	replaced by	3080005402	
100	30.11.2010	3055011800	no longer available		
101	30.11.2010	3054011800	no longer available		
102	24.11.2010	3057438500	replaced by	3057008500	+3424200400 All In Version no longer available
103	24.11.2010	3080007000	replaced by	3080006001	
104	24.11.2010	3080006900	replaced by	3080005901	
105	24.11.2010	3425202600	replaced by	3424200400	All In Version no longer available
106	24.11.2010	2376000400	no longer available		
107	24.11.2010	4200001600	no longer available		
108	24.11.2010	1095204500	no longer available		
109	24.11.2010	4353001300	replaced by	4353001400	
110	19.11.2010	4079000700	replaced by	4079000703	
111	19.11.2010	4079000701	replaced by	4079000703	
112	19.11.2010	4079000702	replaced by	4079000703	
113	18.11.2010	3057007702	replaced by	3057007700	
114	18.11.2010	3057007802	replaced by	3057007800	
115	17.11.2010	662024530	no longer available		
116	08.11.2010	FW17E	replaced by	SK-S 36.20	
117	08.11.2010	FW17EK	replaced by	SK-S36.20W	
118	08.11.2010	FW0E70	replaced by	SK-HD38.36	
119	08.11.2010	FW2E70	replaced by	SK-HD38.36	+ SK-V 36 slider
120	08.11.2010	FW7E40	no longer available		no EC approved replacement available
121	08.11.2010	FW7E90	no longer available		no EC approved replacement available
122	08.11.2010	FW3540	no longer available		no EC approved replacement available
123	03.11.2010	3229002200	replaced by	3228004800	
124	03.11.2010	3229002300	replaced by	3228004900	
125	03.11.2010	3434350200	replaced by	3434350203	
126	03.11.2010	3434350201	replaced by	3434350203	
127	03.11.2010	3434350100	replaced by	3434350101	
128	03.11.2010	4304010200	replaced by	3304010201	
129	03.11.2010	3304010200	replaced by	3304010201	
130	02.11.2010	90508015	no longer available		
131	02.11.2010	90008207	no longer available		
132	13.10.2010	3054001700	no longer available		
133	12.10.2010	xb-01221	no longer available		
134	08.10.2010	FWAL-E-W1-	no longer available		

Modifications in SAF-HOLLAND Original parts numbers: 12.03.2010 – 30.06.2011

	Date	Part number	Note	Part number	Comment
135	08.10.2010	FWAL-E-W2-	no longer available		
136	08.10.2010	3401002200	no longer available		
137	27.09.2010	4175022500	no longer available		
138	19.08.2010	4079001000	replaced by	4079001004	
139	19.08.2010	4079001001	replaced by	4079001004	
140	19.08.2010	3080005500	replaced by	3080005502	
141	19.08.2010	4079001002	replaced by	4079001004	
142	19.08.2010	4079001003	replaced by	4079001004	
143	19.08.2010	4079001700	replaced by	4079001701	
144	19.08.2010	3080005900	replaced by	3080005901	
145	19.08.2010	3080005501	replaced by	3080005502	
146	17.08.2010	1064011100	no longer available		
147	17.08.2010	1064011101	no longer available		
148	17.08.2010	2175007400	replaced by	2175029400	
149	12.08.2010	3005015500	no longer available		
150	05.08.2010	2307200201	no longer available		
151	26.07.2010	4029103200	no longer available		
152	12.07.2010	90036223	no longer available		
153	09.07.2010	1136000500	no longer available		
154	09.07.2010	1136000501	no longer available		
155	05.07.2010	4331220000	replaced by	1331018000	
156	01.07.2010	4304010300	replaced by	3304010301	
157	01.07.2010	4304009300	replaced by	3304009300	
158	01.07.2010	4304009301	replaced by	3304009300	
159	01.07.2010	4304009800	replaced by	3304009800	
160	01.07.2010	4304010301	replaced by	3304010301	
161	01.07.2010	4304010500	replaced by	3304010500	
162	01.07.2010	4304010600	replaced by	3304010600	
163	30.06.2010	1051003200	replaced by	2331016700	
164	30.06.2010	2048103900	no longer available		
165	09.06.2010	4175022900	no longer available		
166	28.04.2010	1402002400	no longer available		
167	28.04.2010	1402003300	no longer available		
168	28.04.2010	3401003300	no longer available		
169	28.04.2010	3401002400	no longer available		
170	28.04.2010	3401001600	no longer available		
171	15.04.2010	3005010100	no longer available		
172	30.03.2010	662101280	replaced by	662101280F	
173	12.03.2010	3307304300	replaced by	3307304301	