



# FIFTH WHEELS

## SERVICE BULLETIN

### Holland HITCH

RK16045J Part Replacement


FW3500, FW351 & FW342

August 11, 2006


Please be aware that the RK16045J compression bush is to be superseded by the RK16045P, blue polyurethane bush.

We currently have approximately 1 months stock on hand as of the above date, once this stock is depleted, all assemblies and bush replacement kits will only be available with the blue polyurethane RK16045P bush.

**RK16045J Compression Bush**



**RK16045P Polyurethane Bush**





*GO THE DISTANCE.*

HOLLAND HITCH (AUST.) PTY. LTD.  
P.O. Box 63 Melton, Vic 3337 Phone: (03) 9743 6799 Fax: (03) 9743 6763  
[www.hollandhitch.com.au](http://www.hollandhitch.com.au)



Quality  
Endorsed  
Company

ISO 9001:2000 Lic 1995  
SIA Group