

SAF Tire Pilot Plus (TPP)

Product Change Notification - Control Box Label Updated with QR Code

Effective Date: January 21, 2021


SAF HOLLAND has enhanced the Tire Pilot Plus control box label with a QR code to allow for immediate access to technical support literature and videos.

The support literature and videos are easily accessed through a QR code decal located on the cover of the Tire Pilot Plus control box.

Decal with QR Code Located on the cover of the Tire Pilot Plus control Box



QR Code Links to TPP Product Support Literature List PDF



Scanning of the QR code with your smart device will serve up a menu list of all available technical support literature and videos for the Tire Pilot Plus. Simply click and open the document or video of your choice.

This change is an enhanced feature for the end user and facilitates immediate access to the necessary support literature to ensure the optimum performance for Tire Pilot Plus - tire inflation management system.

Literature List
SAF® Tire Pilot Plus™
Tire Inflation System

Technical Support Literature List January 2021

This document provides the literature related to SAF Tire Pilot Plus - tire inflation system. Links to literature PDFs are provided below. Call 800.876.3929 to speak with a customer service representative.

Literature Description	Literature PDFs
Installation/Operation Manual	XL-AA20015BM-en-US
Parts Manual	XL-AA20033PM-en-US
Troubleshooting Guide	XL-AA20023TS-en-US
Video Description	Video Link
Installation	INSTALLATION
Troubleshooting	TROUBLESHOOTING

Tire Pilot Plus Tire Inflation System Decal
SAF-HOLLAND provides the warning light decal to the Trailer OEM for installation. If missing or damaged, decal can be ordered through SAF-HOLLAND Customer Service - call 800.876.3929 or email amsales@safholland.com. (Please reference part number and description.)
XL-AA20014DC-en-US - PSI Warning Light (Place this decal below the warning light on the nose of the trailer)

NOTICE

CHECK TIRES AND AIR SUPPLY WHEN LIGHT STAYS ILLUMINATED

illuminated light indicates that the Tire Pilot Plus system pressure could be 20 psi or more below regulator pressure setting and requires service attention.

CLICK AND VIEW LITERATURE AND VIDEO LINKS