

# Literature List

## SAF® Tire Pilot Plus™ Tire Inflation System

### Technical Support Literature List

January 2021

This document provides the literature related to SAF Tire Pilot Plus - tire inflation management system. Links to literature PDFs are provided below. Call 800.876.3929 to speak with a customer service representative.



#### Tire Pilot Plus

Engineering installation drawings are available upon request through SAF-HOLLAND Trailer Suspension Application Engineering - call 888.396.6501.

Literature Description	Literature PDFs
Installation/Operation Manual	<a href="#">XL-AS20015BM-en-US</a>
Parts Manual	<a href="#">XL-AA20033PM-en-US</a>
Troubleshooting Guide	<a href="#">XL-AA20023TS-en-US</a>
Video Description	Video Link
Installation	<a href="#">INSTALLATION</a>
Troubleshooting	<a href="#">TROUBLESHOOTING</a>

#### Tire Pilot Plus Tire Inflation System Decal



SAF-HOLLAND provides the warning light decal to the Trailer OEM for installation. If missing or damaged, decal can be ordered through SAF-HOLLAND Customer Service - call 800.876.3929 or email [amsales@safholland.com](mailto:amsales@safholland.com). (Please reference part number and description.)

**XL-AA20014DC-en-US - PSI Warning Light (Place this decal below the warning light on the nose of the trailer)**

**NOTICE**

**CHECK TIRES AND AIR SUPPLY  
WHEN LIGHT STAYS ILLUMINATED**

Illuminated light indicates that the Tire Pilot Plus system pressure could be 20 psi or more below regulator pressure setting and requires service attention.

XL-AA20014DC-en-US Rev A · 2018-08-30 · Amendments and errors reserved ©SAF-HOLLAND, Inc.