



Important Info – June 2020

HOLLAND® Fifth Wheels

Retirement Notice of FW35 & FW33 Low Lube Top Plate Specification on SDS No-Tilt Base

Effective September 15, 2020

Attention


Effective September 15, 2020, SAF-HOLLAND will retire the FW35 & FW33 low lube top plate specification on SDS No-Tilt base.

OEM orders for the fully assembled fifth wheel products will be accepted until September 15, 2020. Service parts will be available through SAF-HOLLAND Aftermarket for a limited time. Customers should consider the FW35 & FW33 top plate specification on ILS No-Tilt base or the FW70 top plate specification on SDS No-Tilt base as alternatives.


Assemblies affected by this retirement consist of the FW35 & FW33 top plate on SDS No-Tilt base part numbers including all variations and slide lengths.

If you have any questions or require additional product assistance, please contact your account manager or customer service representative.


FW35 & FW33 Top Plate Specification on SDS No-Tilt Base to be Retired



Alternative Options



FW35 & FW33 Low Lube Top Plate Specification on ILS No-Tilt Base



FW70 Top Plate Specification on SDS No-Tilt Base