



SAF-HOLLAND Group

Important Information

Mark V Landing Gear

Product Change Notice for Mark V Landing Gear

September 2019

Attention

This product change notice applies to certain HOLLAND® Mark V Landing Gear.

Product Change:

Effective September 1, 2019, SAF-HOLLAND® will discontinue or change certain foot options currently offered on Mark V landing gear assemblies sold to OEM and Aftermarket customers.

The table below outlines the footwear options that will be discontinued or changed.

OEM and Aftermarket orders for Mark V leg assemblies with discontinued and changing foot options will be accepted until September 1, 2019.

Service parts will be available through the SAF-HOLLAND aftermarket for an extended period of time.

If you have any questions or require additional product assistance, please contact your account manager or customer service representative.

Foot Option Code	Description	Height x Length x Width	Disposition
02	Shock foot	10" diameter	Discontinue, replaced by option code "24"
03	Wheels	9" diameter	Discontinue, no replacement
06	Skid foot	5.0" x 17" x 12"	Discontinue, replaced by option code "07"
07	Skid foot	5.0" x 23" x 12"	Size change to 5.0" x 17" x 12"
08	Skid foot	5.0" x 19" x 14"	Discontinue, replaced by option code "07"
09	Wheels and skid foot	3.8" x 11.5" x 16"	Discontinue, no replacement
23	Low profile skid foot	2.0" x 11.5" x 10"	Discontinue, replaced by option code "13"

