

NEW REPAIR KIT AVAILABLE

REPAIR KIT GREASE CHANGE FOR SAF *INTEGRAL* WHEEL HUB

Rely on SAF quality with our new
SAF Repair Kit Grease Change for *INTEGRAL* wheel hubs



Repair Kit 3 434 3023 00 suitable for Wheel Hub 3 307 3030 01		Repair Kit 3 434 3024 00		Repair Kit 3 434 3025 00	
includes per Kit	for the following Axle Types	includes per Kit	for the following Axle Types	includes per Kit	for the following Axle Types
1 O-Ring	SK RB 9022KI (01)	1 O-Ring	B9	1 O-ring	S9-3718
1 Seal Ring -inner-	SK RB 9019KI	1 Seal Ring -inner-	BA9	1 Seal Ring -inner-	S11-3720
1 Seal Ring -outer-	SK RB 9019WI	1 Seal Ring -outer-	BI9	1 Seal Ring -outer-	S/Z9/11-4218/4220
1 Retaining Ring	SK RB 9022WI	1 Retaining Ring		1 Retaining Ring	SL9-3718
1 Field Spider		1 Field Spider		90 gr. Grease	SL/ZL9/11-4218/4220
90 gr. Grease		90 gr. Grease		5 gr. Grease	SZL11-4218/4220
5 gr. Grease		5 gr. Grease			S/Z7-3015
					Z9/11-3020
					Z9/11-3720
					ZL11-3020/3720
					S19/Z19-19W/19K
					S19/Z19-22W/22K
					S111/Z111-19W/19K
					S111/Z111-22W/22K



Important notice:
Please do always follow SAF instructions for repair and maintenance!

SAF-HOLLAND GmbH

Business Unit Aftermarket · Hauptstraße 26 · 63856 Bessenbach · Germany · Tel +49 6095 301-301

www.safholland.com